


The Tree File Ltd
4 Mulberry Court
Castleknock
Dublin 15
D15 F2V4
Mob. 086-3819011
e-mail - thetreefile@gmail.com

Graphic Representation of Tree Form, balance and Protection Zone



Canopy is drawn to account for any natural asymmetry or imbalance. Crown Representation is scaled to account for north, east, west and south radii.

Root Protection Area (RPA)
This area relates the "RPA" radius as defined in the Tree Survey Table and is measured from the tree centre. This area defines the preliminary Construction Exclusion Zone (CEZ) that must be protected by fencing from the potentially damaging affects of construction activity.

Tree Quality (Categorisation)

- Category "A" Trees (Green Button)
Excellent Quality Trees
- Category "B" Trees (Blue Button)
Good Quality Trees
- Category "C" Trees (Gray Button)
Mediocre to Poor Quality Trees
- Category "U" Trees (Red Button)
Dead, Dying or Otherwise Compromised Trees that are Unsustainable.
- Tree Line
- Hedge or Shrubby

Colour Coding of Tree Retention or Removal

- Trees Intended for Retention - Solid Green Crown Outline
- Trees Intended for Removal In Conjunction With Development Works - Broken Pink Crown Outline
- Hedge or Shrubby to be removed

This Drawing Must Be Read in Conjunction with the Associated Arboricultural Report

Client: 1 Celbridge West Land Limited
Scale: 1:500 @ A1 Date: December 2024
Project: Tree Survey, Fortfield Road, Terenure, Dublin 6W
Description: Tree Impacts Plan
Drawing Title:
Fortfield Road Tree Impacts Plan EAST